

## Byron Unit 2 (January 30, 2012)



- Failed insulator and Loss of Phase 'C' in 345kV switchyard
  - Degraded voltage on 6.9kV and 4.16kV busses caused RCPs and other components to trip
  - 2 of 2 logic required to initiate undervoltage or degraded voltage protection signal was not met
  - Operators manually opened SAT feeder breakers (after 8 minutes)

## **Response Activities U.S.NRC** (Operating Experience Process) **Formal Actions**

Informal Follow-up

## Response Activities (continued) Formal Actions Formal Actions Left Below L

## · How?

sharing OE

 Through formal actions such as event reports, meetings, and generic communications

Because it is a routine, systematic, daily process
 Because we have built relationships across organizational boundaries with an expectation of

 Through informal actions based on the relationships we have developed.



**Backup Slides** 



